

7. Description

Survey No. WA-III-081

Condition

☐ excellent
☒ good
☐ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. The structure is three-bays by one-bay on a fieldstone foundation. The main facade is symmetrically arranged with a central entrance. There is a full-length porch that wraps around the west side of the house. The structure appears to date from the mid-to-late 19th century.

The property is located on the north side of Sandy Hook Road, approximately .05 mile east of Clark Road. The structure sits on a fairly level site slightly back from the road. The main facade faces south.

The two story structure is constructed of frame covered in asphalt shingles. The main facade is symmetrically arranged with a central entrance and one-over-one sash windows in the outer bays of the first and second stories. The central bays of the second story is unfenestrated. The full-length, one-story porch has a hipped roof supported by a square tapered post on brick plinths. The porch continues around the west side of the structure. The gable ends of the structure have one-over-one sash windows in the first and second stories and a small four-paned window in the gable. The house has a boxed cornice and a gable roof covered in asphalt shingles.

8. Significance

Survey No. WA-III-081

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G


Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook Survey District.

WA-III-032, Sandy Hook Survey District

(All prefixes "WA-III-")




WA-III-081

Frame House

18930 Sandy Hook Road (MD 180), Sandy Hook

Harpers Ferry Quadrangle




1993-94 Aerial Photo



FREDERICK & NGTON

HARPERS FERRY, VA-MD-W VA
QUADRANGLE
USGS 7.5 minute map
1:24 000
1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST





1. WA-III-081
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1